

Islandwide Water Level Situation in Major Rivers

DATE : 27-May-2018

TIME : 12.30 AM

River	Station	Coordinate	Catchment Area (km ²)	Unit	Gauging Station			Water Level before 1hr	Water Level at 12.00 Mid Night	Remarks	Water Level Rising or Falling	RF in last 15 hrs mm
					Alert Level	Minor Flood Level	Major Flood Level					
Kelani Ganga (RB 01)	N' Street	6° 57' 35" N 79° 52' 36.6" E	2085	ft	4.00	5.00	7.00	4.05	4.15	Alert	Rising	
	Hanwella	6° 54' 39.38" N 80° 05'	1782	m	7.00	8.00	10.00	5.96	5.91	Normal		11.5
	Glencourse	6° 58' 25" N 80° 11' 3" E	1463	m	15.00	16.50	19.00	12.50	12.48	Normal		27.2
	Holombuwa	7° 11' 6.6" N 80° 15' 53.3" E	155	m	3.00	3.40	5.00	1.69	1.79	Normal		39.6
	Deraniyagala	6° 55' 23.23" N 80° 20'	183	m	4.80	5.80	6.40	1.37	1.36	Normal		12.7
Kalu Ganga (RB 03)	Kitulgala	6° 59' 25" N 80° 24' 50" E	383	m	2.00	3.00	5.00	1.07	1.05	Normal		6.2
	Norwood	6° 50' 8.32" N 80° 36'	97	m	1.50	2.00	2.15	1.04	1.04	Normal		3.2
	Ratnapura	6° 40' 43.2" N 80° 23'	603	m	5.20	7.50	9.50	3.88	3.81	Normal		0.1
	Ellegawa	6° 43' 54" N 80° 13' 4.2" E	1393	m	10.00	10.70	12.20	9.70	9.70	Normal		2.2
	Millakanda	6° 37' 50.3" N 80° 9' 37.7" E	780	m	5.00	6.50	8.00	7.33	7.30	Flood	Falling	1.3
Gin Ganga (RB 09)	Putupaula	6° 36' 51.9" N 80° 3' 44.2" E	2598	m	3.00	4.00	5.00	4.17	4.17	Flood		0.0
	Tawalama	6° 20' 33.3" N 80° 19'	377	m	4.25	4.50	6.10	2.34	2.34	Normal		7.1
	Baddegama	6° 10' 25" N 80° 10' 33.1" E	749	m	3.50	4.00	5.00	3.40	3.37	Normal		0.3
	Pitabeddara	6° 12' 48.2" N 80° 28'	310	m	3.25	4.00	5.00	1.46	1.48	Normal		1.4
	Panadugama	6° 08' 00" N 80° 29' 00" E	445	m	5.00	6.00	6.50	4.98	4.97	Normal		17.8
Maha Oya (RB 102)	Urawa	6° 14' 11.5" N 80° 34' 18" E	59	m	2.50	3.00	4.00	0.91	0.93	Normal		1.4
	Badalgama	7° 18' 3.3" N 79° 58' 50" E	1360	ft	1.00	5.00	16.00	-0.45	-0.55	Normal		4.0
Attanagalu Oya (RB 103)	Giriulla	7° 19' 30" N 80° 6' 53.3" E	1192	m	5.00	6.00	6.50	3.43	3.37	Normal		9.8
	Dunamale	7° 7' 0" N 80° 4' 54.5" E	153	m	3.30	4.40	5.50	5.23	5.23	Flood		15.5



 RECEIVED
 Date : 2018/05/27
 Time : 12:28 PM

Signature

Prepared by : K.G.D.C.Dissanayake
 Checked by : D.A.Somawickrama

Eng.R.M.M.R.Alawathugoda
 Director (Hydrology)