

Islandwide Water Level Situation in Major Rivers

DATE : 20-Dec-2019

TIME : 3.30 PM

River	Station	Gauging Station					Water Level before 1hr	Water Level at 03:00 pm	Remarks	Water Level Rising or Falling	RF in last 6hrs
		Coordinate	Catchment Area (km ²)	Unit	Alert Level	Minor Flood Level					
Kirindi Oya (RB 22)	Tanamalwila	6° 28' 5.9" N 81° 8' 2.8" E	749	m	4.00	5.00	5.50	3.90	4.40	Alert	Rising 32.10
	Wellawayaya	6° 42' 33.3" N 81° 6' 41.6" E	172	m	4.40	5.40	5.90	3.60	4.34	Normal	59.60
Maduru Oya (RB 54)	Padiyatallawa	7° 23' 0" N 81° 11' 30" E	159	m	4.00	4.50	6.00	3.75	3.94	Normal	41.0
	Nakkala	6° 53' 42.4" N 81° 17' 49.3" E	216	m	5.00	6.00	7.50	5.59	6.56	Minor Flood	Rising 96.9
Kumbukkan Oya (RB 31)	Siyambalanduwa	6° 54' 16.5" N 81° 32' 44.4" E	295	m	4.50	5.00	5.60	4.83	4.38	Normal	26.6
	Heda Oya (RB 36)	7° 19' 0" N 80° 59' 18.3" E	4092	m	5.00	6.00	8.00	2.46	2.30	Normal	38.7
Mahaweli Ganga (RB 60)	Weragantota	7° 54' 53.3" N 81° 5' 10" E	7418	m	3.50	3.70	4.00	3.84	3.87	Minor Flood	Rising 2.2
	Taldena	7° 5' 26.7" N 81° 2' 53.3" E	276	m	3.00	4.00	5.00	2.55	2.92	Normal	22.7
Mee Oya (RB 95)	Galgamuwa	7° 58' 13.3" N 80° 15' 18.3" E	299	m	4.84	5.94	7.00	4.72	5.04	Alert	Rising 66.50

Prepared by : K.G.D.C.Dissanayake
Checked by : K.A.Amarasiri

Eng.R.M.M.R.Alawathugoda
Director (Hydrology)
EMERGENCY OPERATIONS DIVISION

RECEIVED

Date : 2019.12.20
Time : 15.01 hrs

D.Ops./DOADO
Signature

DISASTER MANAGEMENT CENTRE