

**Islandwide Water Level Situation in Major Rivers**

DATE : 23-Sep-2019

TIME : 3:30 AM

River	Gauging Station							Water Level before 1hr	Water Level at 3:00 AM	Remarks	Water Level Rising or Falling	Rainfall in Last 6 hrs
	Station	Coordinate	Catchment Area (km <sup>2</sup> )	Unit	Alert Level	Minor Flood Level	Major Flood Level					
Kalu Ganga (RB 03)	Ratnapura	6° 40' 43.2" N 80° 23' 49.8" E	603	m	5.20	7.50	9.50	1.70	1.70	Normal		0.0
	Ellagawa	6° 43' 54" N 80° 13' 4.2" E	1393	m	10.00	10.70	12.20	5.87	5.90	Normal		0.0
	Millakanda	6° 37' 50.3" N 80° 9' 37.7" E	780	m	5.00	6.50	8.00	5.13	5.13	Alert		0.0
	Putupaula	6° 36' 51.9" N 80° 3' 44.2" E	2598	m	3.00	4.00	5.00	1.38	1.36	Normal		0.0
Gin Ganga (RB 09)	Tawalama	6° 20' 33.3" N 80° 19' 55.2" E	377	m	4.00	4.50	6.10	2.75	2.71	Normal		0.8
	Baddegama	6° 10' 25" N 80° 10' 33.1" E	749	m	3.50	4.00	5.00	3.59	3.59	Alert		0.5
Nilwala Ganga (RB 12)	Pitabeddara	6° 12' 48.2" N 80° 28' 34.5" E	310	m	3.25	4.00	5.00	2.07	2.00	Normal		0.0
	Panadugama	6° 08' 00" N 80° 29' 00" E	445	m	5.00	6.00	6.50	6.45	6.42	Minor Flood	Falling	1.4
	Urawa	6° 14' 11.8" N 80° 34' 18" E	59	m	2.50	3.00	4.00	1.29	1.27	Normal		0.0

Prepared by :  
Checked by :

P.A.G.Gayampath  
D.A.Sontawickrema

EMERGENCY OPERATIONS DIVISION

**RECEIVED**

Date : 2019/09/23

Time : 03:30 hrs

*(Signature)*

D (Ops)/DO/ADO

DISASTER MANAGEMENT CENTRE

Eng.R.M.M.R.Alawathugoda  
Director (Hydrology)

Eng. R. M. M. R. Alawathugoda  
Director of irrigation(Hydrology),  
Hydrology Division  
Irrigation Department,  
Colombo 07