

Islandwide Water Level & Rainfall Situation in Major Rivers

DATE : 25-Nov-2021

TIME : 12.30 PM

River Basin	Tributary/River	Gauging Station							Water Level before 1hr	Water Level at 12.00 p.m	Remarks	Water Level Rising or Falling	3 Hr RF in mm at 12:00 pm
		Station	Coordinate	Catchment Area (km ²)	Unit	Alert Level	Minor Flood Level	Major Flood Level					
Malwathu Oya (RB 90)	Malwathu Oya	Tantirimale	8° 35' 13.57" N 80° 16' 31.14" E	2116	m	5.00	6.80	7.80	5.65	5.53	Alert	Falling	6.2
Deduru Oya (RB 99)	Deduru Oya	Ridi bendi Ella (Dam)	7° 43' 36" N 80° 15' 48" E	1370	m	3.30	4.20	4.70	4.45	4.45	Minor Flood		1.2

Prepared by : H.P.S.W.Gunawardhana (H.A.)

Checked by : D.P.M.Alwis (H.A.)

Eng.S.P.C.Sugeeshwara
Director (Hydrology and Disaster Management)