

Islandwide Water Level Situation in Major Rivers

DATE : 22-Sep-2019

TIME : 9:30 PM

River	Station	Coordinate	Gauging Station			Water Level before 1hr	Water Level at 09:00 PM	Remarks	Water Level Rising or Falling	Rainfall in Last 6 hrs	
			Catchment Area (km ²)	Unit	Alert Level						Minor Flood Level
Kalu Ganga (RB 03)	Ratnapura	6° 40' 43.2" N 80° 23' 49.8" E	603	m	5.20	7.50	9.50	1.75	1.77	Normal	0.0
	Ellagawa	6° 43' 54" N 80° 13' 4.2" E	1393	m	10.00	10.70	12.20	5.90	5.88	Normal	1.0
	Milakanda	6° 37' 50.3" N 80° 9' 37.7" E	780	m	5.00	6.50	8.00	5.17	5.16	Alert	0.0
	Putupaula	6° 36' 51.9" N 80° 3' 44.2" E	2598	m	3.00	4.00	5.00	1.50	1.48	Normal	0.0
Gin Ganga (RB 09)	Tawalama	6° 20' 33.3" N 80° 19' 55.2" E	377	m	4.00	4.50	6.10	3.06	2.97	Normal	2.8
	Baddegama	6° 10' 25" N 80° 10' 33.1" E	749	m	3.50	4.00	5.00	3.46	3.48	Normal	6.5
	Pitabeddara	6° 12' 48.2" N 80° 28' 34.5" E	310	m	3.25	4.00	5.00	2.88	2.72	Normal	2.8
Nilwala Ganga (RB 12)	Panadugama	6° 08' 00" N 80° 29' 00" E	445	m	5.00	6.00	6.50	6.61	6.59	Major Flood	6.0
	Urawa	6° 14' 11.8" N 80° 34' 18" E	59	m	2.50	3.00	4.00	1.59	1.51	Normal	1.7

Prepared by : P.A.G. Gayampath
Checked by : D.A. Somawickrama

EMERGENCY OPERATIONS DIVISION

RECEIVED

Date : 2019/09/22

Time : 21.23 hrs

D (Ops)/DO/ADO

Eng.R.M.M.R. Alawathugoda
Director (Hydrology)

[Signature]

D.A.S.
14.9.19

Eng. R. M. M. R. Alawathugoda
Director of Irrigation (Hydrology)
Hydrology Division
Irrigation Department
Colombo 07.