

Islandwide Water Level Situation in Major Rivers

DATE : 9-Oct-2018

TIME : 3.30 AM

River	Gauging Station							Water Level before 1hr	Water Level at 3.00 am	Remarks	Flood Status	RF in last 6 hrs (mm)
	Station	Coordinate	Catchment Area (km ²)	Unit	Alert Level	Minor Flood Level	Major Flood Level					
Kelani Ganga (RB 01)	N' Street	6° 57' 35" N 79° 52' 36.6" E	2085	ft	4.00	5.00	7.00	3.20	3.20	Normal		
	Hanwella	6° 54' 39.38" N 80° 05' 3.16" E	1782	m	7.00	8.00	10.00	3.90	3.96	Normal		10.6
	Glencourse	6° 58' 25" N 80° 11' 3" E	1463	m	15.00	16.50	19.00	11.75	11.70	Normal		0.3
	Holombuwa	7° 11' 6.6" N 80° 15' 53.3" E	155	m	3.00	3.40	5.00	1.06	1.02	Normal		0.0
	Deraniyagala	6° 55' 23.23" N 80° 20' 20.3" E	183	m	4.80	5.80	6.40	1.43	1.37	Normal		0.5
	Kitulgala	6° 59' 25" N 80° 24' 50" E	383	m	3.00	4.00	6.00	1.79	1.74	Normal		0.5
	Norwood	6° 50' 8.32" N 80° 36' 52.75" E	97	m	1.50	2.00	2.15	0.94	0.96	Normal		2.6
Kalu Ganga (RB 03)	Ratnapura	6° 40' 43.2" N 80° 23' 49.8" E	603	m	5.20	7.50	9.50	1.33	1.30	Normal		1.6
	Ellagawa	6° 43' 54" N 80° 13' 4.2" E	1393	m	10.00	10.70	12.20					1.6
	Millakanda	6° 37' 50.3" N 80° 9' 37.7" E	780	m	5.00	6.50	8.00	7.47	7.45	Minor Flood	Falling	0.0
	Putupaula	6° 36' 51.9" N 80° 3' 44.2" E	2598	m	3.00	4.00	5.00	2.94	2.94	Normal		0.0
Gin Ganga (RB 09)	Tawalama	6° 20' 33.3" N 80° 19' 55.2" E	377	m	4.25	4.50	6.10	2.14	2.11	Normal		0.0
	Baddegama	6° 10' 25" N 80° 10' 33.1" E	749	m	3.50	4.00	5.00	4.57	4.55	Minor Flood	Falling	0.6
Nilwala Ganga (RB 12)	Pitabeddara	6° 12' 48.2" N 80° 28' 34.5" E	310	m	3.25	4.00	5.00	0.54	0.54	Normal		0.0
	Panadugama	6° 08' 00" N 80° 29' 00" E	445	m	5.00	6.00	6.50	3.90	3.86	Normal		0.0
	Urawa	6° 14' 11.8" N 80° 34' 18" E	59	m	2.50	3.00	4.00	0.14	0.14	Normal		0.0
Attanagalu Oya (RB 103)	Dunamale	7° 7' 0" N 80° 4' 54.5" E	153	m	3.30	4.40	5.50	2.98	2.94	Normal		0.0

Prepared by : P.A.G.Gayampath
Checked by: K.A.Amarasiri

Eng.R.M.M.R.Alawathugoda
Director (Hydrology)