

Islandwide Water Level Situation in Major Rivers

DATE: 9-Oct-2018

TIME: 3:30 PM

| River | Station | Gauging Station | | | | | | Water Level before 1hr | Water Level at 03.00 pm | Remarks | Flood Status | RF in last 6 hrs (mm) |
|-------------------------|--------------|------------------------------------|-----------------------------------|------|-------------|-------------------|-------------------|------------------------|-------------------------|-------------|--------------|-----------------------|
| | | Coordinate | Catchment Area (km ²) | Unit | Alert Level | Minor Flood Level | Major Flood Level | | | | | |
| Kelani Ganga (RB 01) | N' Street | 6° 57' 35" N 79° 52' 36.6" E | 2085 | ft | 4.00 | 5.00 | 7.00 | 3.20 | 3.20 | Normal | | |
| | Hanwella | 6° 54' 39.38" N 80° 05' 3.16" E | 1782 | m | 7.00 | 8.00 | 10.00 | 4.10 | 4.13 | Normal | 20.8 | |
| | Glencourse | 6° 58' 25" N 80° 11' 3" E | 1463 | m | 15.00 | 16.50 | 19.00 | 11.52 | 11.69 | Normal | 5.9 | |
| | Holombuwa | 7° 11' 6.6" N 80° 15' 53.3" E | 155 | m | 3.00 | 3.40 | 5.00 | 1.74 | 1.79 | Normal | 43.7 | |
| | Deraniyagala | 6° 55' 23.23" N 80° 20' 20.3" E | 183 | m | 4.80 | 5.80 | 6.40 | 1.35 | 1.35 | Normal | 3.7 | |
| Kalu Ganga (RB 03) | Kitulgala | 6° 59' 25" N 80° 24' 50" E | 383 | m | 3.00 | 4.00 | 6.00 | 1.88 | 1.88 | Normal | 9.8 | |
| | Norwood | 6° 50' 8.32" N 80° 36' 52.75" E | 97 | m | 1.50 | 2.00 | 2.15 | 0.91 | 0.91 | Normal | 2.3 | |
| | Ratnapura | 6° 40' 43.2" N 80° 23' 49.8" E | 603 | m | 5.20 | 7.50 | 9.50 | 2.17 | 2.21 | Normal | 0.0 | |
| | Ellagawa | 6° 43' 54" N 80° 13' 4.2" E | 1393 | m | 10.00 | 10.70 | 12.20 | 7.40 | 7.46 | Normal | 3.3 | |
| | Millakanda | 6° 37' 50.3" N 80° 9' 37.7" E | 780 | m | 5.00 | 6.50 | 8.00 | 7.32 | 7.32 | Minor Flood | 2.0 | |
| Gin Ganga (RB 09) | Putupaula | 6° 36' 51.9" N 80° 3' 44.2" E | 2598 | m | 3.00 | 4.00 | 5.00 | 3.00 | 3.00 | Alert | 6.0 | |
| | Tawalama | 6° 20' 33.3" N 80° 19' 55.2" E | 377 | m | 4.25 | 4.50 | 6.10 | 3.15 | 3.10 | Normal | 14.7 | |
| | Baddegama | 6° 10' 25" N 80° 10' 33.1" E | 749 | m | 3.50 | 4.00 | 5.00 | 4.56 | 4.56 | Minor Flood | 0.8 | |
| Nilwala Ganga (RB 12) | Pitabeddara | 6° 12' 48.2" N 80° 28' 34.5" E | 310 | m | 3.25 | 4.00 | 5.00 | 1.21 | 1.23 | Normal | 4.4 | |
| | Panadugama | 6° 08' 00" N 80° 29' 00" E | 445 | m | 5.00 | 6.00 | 6.50 | 4.18 | 4.30 | Normal | 1.7 | |
| | Urawa | 6° 14' 11.8" N 80° 34' 18" E | 59 | m | 2.50 | 3.00 | 4.00 | 0.54 | 0.56 | Normal | 4.7 | |
| Attanagalu Oya (RB 103) | Dunamale | 7° 7' 0" N 80° 4' 54.5" E | 153 | m | 3.30 | 4.40 | 5.50 | 3.22 | 3.36 | Alert | 28.8 | |

Eng. R. M. M. R. Alawathugoda
Director of Irrigation (Hydrology)
Hydrology Division
Eng. R. M. M. R. Alawathugoda
Director of Irrigation Department
Director (Hydrology)
Colombo 07.

Time: 09/10/18 15:37
D (Ops)/DC/ADO
EMERGENCY OPERATIONS DIVISION
15.37
D (Ops)/DC/ADO
MANAGEMENT CENTRE

Prepared by: K.G.D.C. Dissanayake
Checked by: D.A. Somawickrama